

TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R024X - 3-IN-1 PERFORMANCE JACKET

	S	M	L	XL	2XL
UK (full chest in inches)*	38	41	44	47	50
German clothing size (men)	48	50	54	56	60

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm